



CheckGaadi.com Inspection Report

Order# [CG-BLR-XXXXX]

Inspection Date— 14-Apr-2015

Vehicle Details

Registration#	KA 01 AB XXXX	Fuel	Diesel
Vehicle Make	Volkswagen	Model	Vento
Manufacture Year	2011	KM Reading	20,021
Chassis Number	XVRT14699BZ014650	Engine Number	GKJKLU172621
Test Drive Taken	Yes	No. of Owners	2

Quality Wheel





Inspection Summary



	Engine		Good	
	Battery		Very Good	
	Suspension		Average	
	Tires		Average	
	Electrical		Good	
	Transmission		Very Good	
	Interiors		Poor	
	Exteriors		Poor	
	Accessories		Very Good	
	Brakes		Very Good	
	Steering		Very Good	



Projected Expenses

What	When	How much
General servicing	Now	3,000
Rear RH suspension	Now	3,000
Driver seat belt	Now	1,500
Tinkering and painting	Optional	5,000
Hosepipe replacement	1 month	2,500
Jack & spanner	Now	1,000
Total		62,500

Priority Observations

- RH shock absorber is not functioning
- Painting and tinkering work needed over full body
- Signs of repainting on LH mudguard and boot
- Floor matting and boot cover in cabin to be changed
- Both rear doors need beading replacement
- On hard brake car is skidding. Not recommended to take the car outstation or on long drives without repairs
- Rear mirror covers need repainting
- Coolant leakage observed
- Hosepipe leakage observed
- Car needs through servicing

Minor observations

- Misalignment between headlamp and bonnet. Has gaps
- RH fitting holding the bumper is broken
- Mat under the bonnet needs replacement
- No jack or spanner present in the boot
- Driver seat belt is broken
- Several indicator bulbs are dysfunctional



= No issues



= Minor issues



= Major issues



= Not available



Engine



Oil leakage



Hose pipes



Air filter



Belt condition



Engine oil



Fuel pump (Diesel)



Silencer



Plugs (Petrol)



Radiator



Coil (Petrol)



Battery



General condition



Reputed brand



Original



Corrosion



Suspension



Uniform vehicle level



Consistent recoil



Creaking noise



Driving experience



Tires



Smooth wear and tear



Reputed brand



No cuts or bubbles



Rim condition



Electrical



Self start



Rear defogger



Air conditioning



Courtesy lights



Heating



Warning light



Wipers



Fog lights



Horn



All lamps



Fan noise levels



All switches



Sample Report



Transmission



Differential fluid leakage



Smooth gear shifts (Manual)



Reverse grinding noise



Clutch (Manual)



Axle noise



Transmission fluid (Auto)



Interiors



General cabin condition



Central locking



Cleaning and polishing



Seat belts



Instrument panel gauges



Seat adjustments



Mirror adjustments



Seat covers



Windows adjustments



Dashboard warning



Exteriors



Paint quality



Manual locking



Signs of repainting



Windshield cracks



Signs of major accident



Trunk and bonnet alignment



Wiper blades



All panels alignment



Doors operation



Dents and scratches



Accessories



Audio system & speakers



Car alarm



Remote locking



Reverse camera/sensors



Brakes



Brake fluid leakage



Brake shoes/grinding noise



Hand brakes



ABS



Sample Report



Steering



Steering lock



Vibrations



Rack & pinion



Swaying



Noise during turn



Resistance during turn



Vehicle Documents



Valid insurance



Compare VINs



Life time tax paid



No remarks present in RC



Original RC book



No stolen vehicle records





Government of India
Ministry of Home Affairs
National Crime Records Bureau

Motor Vehicle Verification

East Block-7, R.K. Puram,
New Delhi - 110066

Dated: 14/04/2015 10:23:12
Reference No. 1297651

Vehicle Enquiry Report
Only For Information For General Public
(Not Valid For Insurance Claims/Any other Legal Purposes)

Reference enquiry received from Mr./Mrs. CG regarding

Vehicle Type : CAR

Make : [REDACTED]


Registration No. : [REDACTED]

Chassis No. : [REDACTED]

Engine No. : [REDACTED]

As per the information available with NCRB till date (based on data received from States/UTs police) the above mentioned vehicle **has not been reported as stolen**.

Databank maintained by NCRB updated on 14/04/2015 1297651 10.23.73.12 printed on 14/04/2015



FRONT

REAR

● Dent ● Scratch ● Rust

- This report is created by CheckGaadi.com after physical inspection of the vehicle and is based on the best judgment of technicians at the time of inspection without any prejudice. Errors, if any, are unintentional and shall be brought to our notice at the earliest.
- This report shall be used only as an input in the overall decision making process and should not be considered as sole decision making criterion or the final recommendation for purchasing or not purchasing.
- This report is created for the sole consumption of the party to whom it is originally distributed and shall be used at their personal discretion. CheckGaadi.com, its subsidiaries, partners or parent company shall not be held responsible for any real or perceived loss caused by the use of this report by anyone, or by the inability of CheckGaadi.com or its partners in not being able to discover some issues.
- CheckGaadi.com does not claim to have verified complete vehicle documentation and its authenticity. Our focus area is restricted to the quality assessment of the vehicle only.
- Any services delivered by partners of CheckGaadi.com are subject to their respective terms of service. Please refer to <http://www.checkgaadi.com/terms-of-service/> for additional details.
- The inspection may not be able to uncover sporadic or hidden issues, and problems which can only be identified after removing vehicle parts. Some checks are subject to the vehicle owner's consent for a test drive.