

## COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 15, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Craig County Giles County	STA 11471+52 – 11353+67 MVP-CR-258.01 MVP-GI-256.02	Weather:	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Background:** This investigation was conducted in response to an email received on April 13, 2020 for the ROW along the Craig County and Giles County line.

- The complaint describes inadequate erosion control within the MVP ROW.

**Observations:**

- Approximately 1" precipitation accumulation on 4/12 and 2" on 4/13 recorded in the area prior to inspection.
- Several maintenance items were noted during the inspection (Figures 5-8)
- ROW from STA 11353+67 to 11471+52 was stabilized with straw. No significant erosion was noted within the LOD at the time of inspection.
- No evidence of sediment discharge off ROW was found during the inspection.
- Topsoil stockpiles were stabilized in accordance with Minimum Standard 2 and MVP PSS&S.

**Comments:** ROW inspected in Giles and Craig County from STA 11353+67 through STA 11471+52.

- The following resources were inspected during the onsite complaint investigation: S-CD14, S-OO12, S-OO13, S-OO14, W-CD12 and S-KL43. No impacts were found.
- Stabilization techniques used are in compliance the approved Project Standards and Specifications.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 11438+00: Cleanout/maintain rock inlet protection.
- STA 11435+00: Maintain/repair CFS.
- STA 11436+00: Repair and stabilize minor erosion caused by stormwater run-on.
- STA 11410+00: Repair and stabilize minor erosion caused by stormwater run-on.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** **Wednesday, April 15, 2020**

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, April 15, 2020

**Figure 1: Stream S-0014** – Controls in place and functioning properly around stream S-0014. Area stabilized with straw. Stockpiles stabilized.



**Figure 2: STA 11414+00** – Controls in place and functioning properly. Area stabilized with straw. No erosion evident. Stockpiles stabilized.



**Figure 3: STA 11398+00** – Controls in place and functioning properly. Area stabilized with straw. No erosion evident. Stockpiles stabilized.



**Figure 4: STA 11382+00** – Controls in place and functioning properly. Area stabilized with straw. No erosion evident. Stockpiles stabilized.





## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, April 15, 2020

**Figure 5: STA 11438+00** – Slope drain inlet protection maintenance needed.



**Figure 6: STA 11436+00** – Repair and stabilize minor rill erosion caused by offsite stormwater run-on.



**Figure 7: STA 11435+00** – CFS maintenance needed.



**Figure 8: STA 11410+00** – Repair and stabilize minor rill erosion caused by offsite stormwater run-on.

