

FR


REPORT OF DAMAGES

DE : Dented BR : Broken
 PE : Perforated SC : Scratched
 BU : Burned MI : Missing
 RI : Ripped TN : Torn
 FO : Folded SP : Splinter

DATE	CONTRACT	UNIT	PARKING
2012-06-23	00081205	1552	

Client
 ANGERS TOYOTA

Make /Model
 Toyota Corolla



ACCESSORIES			KILOMETER		TIRE CONDITION		
Departure	Quantity	Return	Departure	Return			
	Trolley			Spare tire	Kilometer upon	<input type="text"/>	<input type="text"/>
	Blankets			Jack	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Straps			Lighter	Kilometer upon return:	<input type="text"/>	<input type="text"/>
	Flares			Cap	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Snow Brush			Snow carpets	<input type="text"/>	<input type="text"/>	<input type="text"/>
		<input type="checkbox"/> Front					
							<input type="checkbox"/> Rear
<p>The accessories and damages on this checklist were noticed at the point of departure.</p> <p>I agree to return the vehicle in the same condition that it was delivered to me or otherwise pay for the cost of repairs.</p> <p>Custom _____</p> <p>Employee: _____</p>					GAS		
					Reading upon delivery		Litres of gas
					E	1/4	1/2
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					Reading upon return		Litres of gas
					E	1/4	1/2
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
					<p>The client agrees to return the vehicle with the same amount of gas as when it was delivered. The client agrees to pay _____ for each 8th of gas missing upon the return of the vehicle.</p>		
<p>The accessories and damages listed on this sheet have been verified at the time of return.</p> <p>Customer _____</p> <p>Employee: _____</p>					<p>Customer: _____</p>		