

PHOTOGRAPHS



Photograph 1: Valve cluster at approximately 16+50 on road "B".



Photograph 2: Large pile of surplus soil in location of proposed hydrant at approximately Sta. 16+75 and further.



Photograph 3: Stabilized construction entrance at the end of Phase I. Sediment being tracked onto road.



Photograph 4: Stabilized construction entrance at Sta. 3+50 road "B". Earthen path bypassing construction entrance.



Photograph 5: Proposed cistern location.

